

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : CHAMBERS COUNTY SEED
LOCATION : WINNIE, TEXAS
SITE NUMBER: TXD981600596
SURVEY DATE: 1989 INSPECTED BY: STATE FIT TAT OTHER: _____
LABORATORY : CLP EPA OTHER _____

RECEIVED FROM: Betty Williamson

DATE RECEIVED: 09/01/94

SAMPLE TYPE(s):

SOIL SURFACE WATER GROUND WATER DRINKING WATER
off / on -site off / on -site off / on -site off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological

FOLLOW UP (Y/N):

N (Re)Sampling Requested N Locate Drinking Water Sources
N Further Action is URGENT N Keep Site Active ("N"=No Further Action)
Y Concur with Report Recommendations

SUMMARY:

According to the attached information, the site is an active facility and a RCRA non-filer. Ground water is used for drinking purposes within the 4-mile target distance limit of the Ground Water Migration Pathway. The location of water wells have not been documented. Approximately 5000 individuals obtain drinking water from the wells within the target distance limit. Surface water drainage into a perennial surface water body is not known.

RECOMMENDATION:

Based on the available information, the drinking water wells need to be documented.

Concurrence:

Hellol K. Rong 09,06,94
ENGINEER/REVIEWER

_____/____/____

9647028

